

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,800,140 B2
DATED : October 5, 2004
INVENTOR(S) : Samuel N. Hansen

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7.


Line 19, reads "the reed switch 46 is fixed an a location" should read -- the reed switch 46 is fixed on a location --.

Column 11.

Line 32, reads "to the surface to be" should read -- to the surface to be cleaned; --.

Signed and Sealed this

Sixteenth Day of August, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office